## 3.2 Condition Analysis Matrix

	Alamosa Sch													
	Elementary												Date of last Addition: N	A
Date: 11/3/2023									Year round start date:					
Failure Timing L	_egend													
1		iate Action (Red)											2	
	2 Replace within 5 Years (Orange) 3 Replace within 6-10 Years (Yellow) (see scoring tab for details)							GCs and Fee						
		,	iso indicate remain years of system life			_	(see scorir	ig tab for detail	s)				Contingency Amoun	t 15.00%
	•	, ,											Soft Cost	
					Condition Matrix	<b>↓</b>					-	-	-	-
						FAIL			FINAL	REMAINING	COST (Direct Cost)	COST (w/ Fees & GC's)	TOTAL COST	TOTAL COST
ITEM #	FACILITY	LOCATION	ITEM DESCRIPTION	CONSULTANT		TIMING	CAT	CONSQ	RANK	LIFE (YEARS)	(no soft costs)	(no soft costs)	(w/ soft costs)	(w/ contingency)
12	ESK2	INT	Replace receptacles with Tamper Resistant Receptacles	ELEC/I.T.	Electrical	1	3	1	3	10	0 \$ 13,00	00 \$ 14,95	0 \$ 17,940	\$ 20,182.50
1	ESK2	ROOF	Beer falle discharge aus auf die state in 1949 van die Balter aus die sta	ARCH		4	0	0	6		\$5,00	\$ 5,75	0 \$ 6,900	\$ 7,762.50
00	501/0		Provide drainage away from the building at all down spouts		EXT-Roof	1	2	3	0				0. 0. 100	* 00.000 F0
22	ESK2	INT	Replace existing door hardware to have push button locks (at classrooms or student	ARCH ARCH	Safety and Security	1	1	8	8		0 \$ 45,00 \$1,50	. ,		
2	ESK2 ESK2	EXT	Provide corner and wall protection at the trash enclosure		EXT-Wall Electrical	1	3	3	9 12			, ,		
11 18	ESK2 ESK2	EXT INT	Replace damaged weather proof enclosure for outdoor receptacle	ELEC/I.T. MECH	HVAC	1	3	3	12	4	2 \$ 52 \$ 5,00			
16	ESK2 ESK2	EXT	Add exhaust fan in boiler room for temperature control	ELEC/I.T.	Communication	1	4	5	20		\$ 5,00 7 \$ 85,00			
17	ESK2 ESK2	INT	Replace aging cameras with current model replacements from iPRO/Advidia - exterior	ELEC/I.T.	Communication	1	4	5	20	1(	0 \$ 234,00			
6			Modernize/Upgrade Audio-Visual Systems in classrooms (approx. 36 classroom spaces).			1								
-	ESK2	EXT	Refill low grade around building perimeter	ARCH	EXT-Wall	2	2	6	24		\$25		8 \$ 345	
7	ESK2	EXT	Provide gutter or splash pads at the north elevation below metal roofs	ARCH ARCH	EXT-Wall	2	2	6	24		\$3,50	+ .,+=		
5	ESK2	EXT	Adjust landscape sprinklers to spray away from the building, Deterioration of brick walls		EXT-Wall	2	6	-	36					
10	ESK2	EXT	Replace damaged wireway enclosure for PV system	ELEC/I.T.	Electrical	2	6	3	36		\$ 50			
20	ESK2	ROOF	Support vertical ductwork in mechanical mezzanine.	MECH	HVAC	2	6	3	36	-	\$ 60			\$ 931.50
15	ESK2 ESK2		Replace aging cameras with current model replacements from iPRO/Advidia - interior	ELEC/I.T.	Communication	2	4	5	40		7 \$ 85,00			
13 8	ESK2 ESK2	INT EXT	Upgrade fire alarm system to voice capability. Functioning currently, but state strongly Replace pole mounted fixture head.	ELEC/I.T. ELEC/I.T.	Safety and Security Lighting	4	3 7	4	48 49		\$ 295,3 <sup>2</sup> 5 \$ 2,00			
4	ESK2	ROOF	Remove all stored card board boxes from roof area	ARCH	EXT-Roof	2	4	7	49 56	`	\$2,00			
3	ESK2	EXT	Clean rust from trash enclosure structure and repaint	ARCH	EXT-Wall	2	4 6	6	72		\$75	•		
5	LONZ	LAI	Upgrade existing telecommunications rack in Mechanical mezzanine - even though the	/		2	0	0	12		ψr.	φ 00	φ 1,000	φ 1,104.30
		INT	installation of equipment is clean and neat, this equipment should be in a cabinet instead	ELEC/I.T.	Communication	4	6	3	72					
14	ESK2		of an open frame rack. This would provide protection to equipment. Cabinet should have							2	2 \$ 7,50	00 \$ 8,62	5 \$ 10,350	\$ 11,643.75
			exhaust fans, temp sensors and ground provisions											
			Upsize louvers serving ERVs to allow for lower velocity on intakes			_								
19	ESK2	INT		MECH	HVAC	3	7	7	147		\$ 1,72	25 \$ 1,98	4 \$ 2,381	\$ 2,678.06
			Replace fluorescent lighting with LEDs and upgrade controls. System is functioning, but											
9	ESK2	INT	upgrade would comply with code.	ELEC/I.T.	Lighting	4	11	6	264	ł	5 \$ 516,80	03 \$ 594,32	3 \$ 713,188	\$ 802,336.66
<u>.</u>			Repair slab cracks: Minor slab and masonry cracking in several locations. While not of					_						
21	ESK2	INT	structural concern, could repair/replace to correct aesthetically	STRUCT	INT-Wall Construction	4	11	7	308		\$ 30,00	00 \$ 34,50	0 \$ 41,400	\$ 46,575.00
23	ESK2													
24	ESK2													
25	ESK2													
										-		· · ·		
										Condition	Totals	Totals	Totals	Grand Totals
										0-25	\$ 392,77			
										26-50	\$ 383,66			
										51-100	\$ 8,50			
										> 100	\$ 548,52			
										Totals ->	> \$ 1,333,46	9 \$ 1,533,489	\$ 1,840,187	\$ 2,070,211

Condition	Т
0-25	\$
26-50	\$
51-100	\$
> 100	\$
Totals ->	\$

GCs and Fees	15.009
Contingency Amount	15.009
Soft Cost:	20.009