Condition Photo Documentation

Pagosa Springs High School

09/27/2024

	LAYER 1: BOUNDARY & TRAFFIC FLOW	
	Image	Comment
a		There is not a marquee / signage indicating the school's name near the primary entry.
b		Most of the paved areas were in acceptable condition. There are some areas along the southern access drive where parking was observed on gravel and some patch repair obvious.
c		The administration does not have views to the exterior. There is a security desk in the entry vestibule that provides some opportunities for natural surveillance.

Condition Photo Documentation, continued

Pagosa Springs High School

	LAYER 2: OUTDOOR SPACES & AMENITIES	
	Image	Comment
а		Bike racks are located in an area that is NOT easily monitored throughout the day. Bikes observed chained to railing at entry.
b		There is a geodesic that could be used for outdoor instructional space and is appropriate for the cold climate.
C		The route to the play and field areas are NOT ADA accessible.

Archuleta County 50 JT School District | Educational Adequacy Assessment

Condition Photo Documentation, continued

Pagosa Springs High School

	LAYER 3: ADMIN & STAFF SPACES	
	Image	Comment
а		Collaboration spaces are NOT providing faculty with furnishing and technology to support small and large group gatherings.
b		<i>The lounge(s) is small for the number of staff members.</i>
С		Nurse office is remote from the administration area and has no passive surveillance.

Archuleta County 50 JT School District | Educational Adequacy Assessment

Pagosa Springs High School

	LAYER 4: CORE & SHARED SPACES	
	Image	Comment
а		Traditional tables and chairs were observed.
b		The library is "traditional" in nature and lacks flexibility.
C		There were a lot of materials being stored in the primary art space, indicating a need for additional or more efficient storage.

Condition Photo Documentation, continued

Pagosa Springs High School

	LAYER 5: CLASSROOMS & TEAMING AREAS	
	Image	Comment
a		There is NO Teaming Area for cross collaboration between students or subject matters.
b		No locking function on the interior side of classrooms was observed.
c		Fixture output quality varies. Many spaces had un-even light distribution and are incandescent.