

PROJECT: Ouray School District – Gymnasium Facilities Master Plan

PROJECT NO: 2024-033.00

DATE: 10/01/2024

ATTENDANCE: See Attached Attendance Sheet

SUBJECT: PAT Meeting #3

Spt. Tod Lokey kicked off the meeting with a brief introduction to the process.

Brian Calhoun gave a brief background of RTA and our past experience working at the Ouray School District, namely the 2015 Facilities Master Plan that lead to the 2016 renovation project at the main building. The following is an outline of the material covered in the meeting:

- 1. Brian reviewed the outline schedule for the master planning process which is intended to conclude late fall of 2024.
- 2. Brian reviewed the facility assessment process including a summary of findings and the total estimated cost of facility deficiencies currently just over \$3M. Refer to attached slides for details.
- 3. Brian reviewed the educational adequacy assessment including a brief description of of the safety and security review of the facility. Various facility areas were scored and a summary of scores was provided indicating relatively low scores for Restrooms, Kitchen/Cafeteria, Gymnasium (lowest of the scores), Locker Rooms, and Wood Shop. A summary of findings was reviewed with the group as well as general discussion with the attendees about other facility challenges that the district faces. Comments from the Group were documented on a flip chart and can be summarized as follows:
 - a. Locker Rooms: Visiting teams do not have direct access to restrooms from the locker room areas (creating confusion and is an ongoing management issue).
 - b. Pipes have been freezing in the crawl space due to old valves failing and creating situations with the heating system being stuck on or off.
 - c. There is not adequate runout space around the basketball court and not space for cheer leaders.
 - d. There is a lack of storage space for PE and athletics as seem by the items stored on the side of the court.
 - There is no compliant room for officials they use the weight room but do not have restrooms.
 - f. There is no real dedicated concessions (students do this out of the main kitchen area).
 - g. It was asked if a snow melt system could help manage snow and ice that accumulates on the north side of the gymnasium.
 - h. There is interest in expanding opportunities for CTE programs including trades.
 - i. Currently the Art program provides CTE opportunities for students but lacks storage space for materials to support this.
 - j. A space that could support Life Skills instruction such as a kitchen would be beneficial (has done this in the main kitchen in the past).
 - k. It was noted that the cafeteria is loud and is a little small for the largest lunches.
 - I. The idea of creating spaces that are shared could help the school manage space and maximize offerings.
 - m. An place that could accommodate indoor recess would be appreciated.
 - n. The music room would benefit from more practice rooms and better room acoustics.
 - o. The music room can not accommodate large item delivery very easily.

19 South Tejon Street, Suite 300 - Colorado Springs, CO 80903 - Tel: 719-471-7566 Fax: 719-471-1174

- p. It was mentioned that moving Choral program out of the main building might make sense and free up a room inside the main school.
- 4. Brian reviewed some design considerations for kinds of spaces currently housed in the Gymnasium building.
- 5. Brian reviewed the top western slope CTE program themes. It as mentioned that some feel that the school needs to focus on executing their current curriculum better and not expand. It was also mentioned that it may be wise to plan for some growth and consider what program expansion might make sense.
- 6. Brian reviewed some concepts on how you might make flexible use of space to offer more programs while keeping the overall square footage down.
- 7. Brian reviewed four options to address issues at the current Gymnasium building and discussed pros and cons for each option. A fifth option was discussed by the group as is summarized below:
 - a. Option 1: Maintenance
 - i. Pros: Lowest cost
 - ii. Cons: Does not address functional issues with building
 - b. Option 2: Maintenance and Renovation
 - . Pros:
 - ii. Cons: Pre Engineered Metal Building is limiting in terms of what renovations, likely to find unknowns that add project risk, difficult to make any significant functional changes to building, possibly putting good money into a bad building
 - c. Option 3: New Building on Existing Site
 - i. Pros: Offers ability to address many functional needs, could improve curb appeal of this building and create a unified campus
 - ii. Cons: High cost of project would require a grant as the district could not raise enough to fund the whole project, project would displace gym/cafeteria and classrooms for over 1 year (this would be very hard)
 - iii. renovated and is that a good investment?
 - d. Option 4: New Building on existing Playground site
 - i. Pros: Is a better location on same side of street, avoids going a year without gym/cafeteria, maybe convert old gym to indoor play facility?
 - ii. Cons: Same as option 4
 - e. Option 5: New Building on another site
 - i. Pros: could result in having two gyms which would be advantageous for scheduling practices, allows existing building to remain in service during project
 - ii. Cons: What happens with old gym building after new one is built? Is it
- 8. A straw poll was conducted and the preferred option is to replace the existing building on the playground site.
- 9. The group also discussed a few items to consider:
 - a. The school might grow to 200 students or about 15 students per grade.
 - b. The music room should be located such that it can have tall ceilings.
 - c. Consider using 7th street for potential building or playground. It was noted that this was objectionable to the town and community in the past. Sentiment might be different today?
- 10. The group discussed that more information is needed on the impact of a potential school bond and how sunsetting mill levy (2026) might factor into the equation.
- 11. It was mentioned that the timeline for a best grant application is January each year. Most communities secure a grant first and then go for a bond using the grant to promote the issue.
- 12. It was noted that most of the replacement building options would require a grant in addition to a local Bond Measure.

Attachments: PAT#3	3 PowerPoint Slides		
CC: File			
CC. Tile			
REPORTED BY:		Brian Calhoun, AIA	
	Signature	Printed Name	

Ouray School District R-1 Developing Minds to Match Our Mountains

P.O. Box N 400 7th Avenue Ouray, CO 81427

Phone: 970-325-4505 **Fax:** 970-325-7343 Website: www.ouray.kı2.co.us

OURAY SCHOOL DISTRICT R-1 MEETING SIGN-IN

DATE: 10/01/2024

Name	Email
Rose Giveisz	
Jane Schiffer	
Pam Larson	
Jay herdestale	
DON MORT	
Kenneth Nelsa	
CRAIG HINKSON	
Ella Skoloda	
Melissa Demuth	
Jeep Demuth	
Stophanie Wills	
Jimmy Chiang	





Ouray School District – Gymnasium Master Plan October 1, 2024







40+

District-wide Master Plans / Facility Assessments

20+

Rural School District Master Plans / Facility Assessments

6M+

Square feet assessed in the past 6 years

Academy District 20 Facilities Assessment

Archuleta School District Master Plan

Arriba-Flagler School District Facility Assessments

Brighton School District 27J Master Plan

Burlington School District RE-6J Master Plan

Calhan School District Master Plan

Campo School District Master Plan

Cheyenne County School District Master Plan

Cheraw School District Master Plan

Colorado Springs District 11 Facilities Assessment Index Audit

Colorado Springs School Master Plan

East Otero School District Master Plan

Early Connections System-Wide Master Plan

Fowler School District Master Plan

Gunnison Watershed School District Master Plan

Hanover School District Master Plan

High Mountain Institute Master Plan

Hinsdale School District Master Plan

Hoehne School District #3 Facility Assessments

Holly School District Master Plan

Ignacio School District Master Plan

Las Animas School District Master Plan

Lewis-Palmer District #38 Master Plan

Montrose County School District Master Plan

Mountain Valley School District Master Plan

Ouray School District Master Plan

Peyton School District Master Plan

Platte Canyon RE-1 District Master Plan

Pueblo District 70 Facilities Needs Assessment

Ridgway School District Master Plan

Roaring Fork School District Master Plan

Springfield School District RE-4 Master Plan

Strasburg School District Master Plan

The Colorado School for the Deaf and the Blind Master Plan

Trinidad School District Master Plan

Vilas School District Master Plan

A Living Road Map for Future Planning

- ✓ Provides a strategy for a unified cohesive approach, integrated with the community
- ✓ Assessments of facility inventory and building aligned with mission and pedagogy.
- ✓ Educational Adequacy and Safety/Security Assessments
- ✓ Develop a Space Program for Gymnasium Building
- ✓ Develop design options (may include renovations and new)
- ✓ Invites broad stakeholder input
- ✓ Evaluate Funding options and Time lines
- ✓ Provides the basis for data-driven decisions against known benchmarks
- ✓ Supports your communication process
- ✓ Supports your students' success

June July August September October November 2024

Phase A – Discovery & Investigation

Gather Information
Existing Facility Assessment & Verification
Kick-Off Meeting (Today)

Phase B - Synthesis

RTA Team data analysis
(Compile data and cost information)
Draft Program

Phase C – Master Plan Options

Present Options/Cost Models, Fall 2024 Select Preferred Options, Fall 2024

Phase D – Master Plan Completion

Submit Final FMP to School Board, Fall 2024

Ongoing FMP Support

Best Grant Application: Jan – Feb. 2025 or 2026 Bond or MLO Support: March – Nov. 2025 or 2026

Step One:

Understanding Facility Conditions

GYMNASIUM BUILDING (2014 Assessment)









RTA Identified Issues

- Envelope Damaged and aged (north, east and west sides)
- Roof not designed for snow and ice accumulation
- Kitchen Exhaust poorly routed and has no ansul
- Kitchen equipment beyond life expectancy
- Drainage issues at courtyard
- Retaining wall at courtyard failing
- Lack of adequate dust collection system

GYMNASIUM BUILDING (2024 Assessment)









RTA Identified Issues

- Envelope Damaged due to ice from roof
- Need Fire Alarm devices at wood shop
- Need to Replace HVAC
 Equipment (pipes freezing from failed valves)
- Limited Gym Floor Life Remaining
- Lack of Fire Sprinkler
- Poor Energy Performance

3.2 Condition Analysis Matrix

District: Ouray School District
Facility: Ouray Gymnasium
Date: 6/20/2024

(see scoring tab for details)

Failure Timing Legend

- Needs Immediate Action (Red)
 Replace within 5 Years (Orange)
 Replace wihtin 6-10 Years (Yellow)
- 4 Improvement Item (Green) Also indicate remaing years of system life

i	
Contengency Amount	15.00%
Soft Cost:	20.00%

						FAIL	FINAL		FINAL REMAININ		COST (Direct Cost)	OST (Direct Cost) COST (w/ Fees & GC TC		TOTAL COST
ITEM # ▼	FACILITY *	LOCATIO 🔻	ITEM DESCRIPTION	CONSULTANT *	ITEM CATEGORY ▼	TIMIN(*	CAT ▼	CONS.	RANK √	LIFE (YEA	(no soft costs) ▼	(no soft costs) ▼	(wł soft costs) ▼	(w/ contengenc ▼
	Gymnasiu		Add carbon monoxide sensors to gym and boiler room (UL 2034, cheap	ME+E	HVAC System	4	4	4	4	0	\$ 120	\$ 144	\$ 173	\$ 194.40
	m		plug-in type w/ battery backup)	IVIETE	HVAC System	'	'	'	' '	U	\$ 120	J 144		
	Gymnasiu		Add GFCI protection at coffee counter receptacles in the cafeteria	ME+E	Electrical - Distribution Syst	4	1	4	4		\$ 1,436	\$ 1,723	\$ 2,068	\$ 2,326.32
	m			IVILTL	Electrical - Distribution Syst	'	'	'	'		ψ 1,430	1,723		
	Gymnasiu		Add GFCI protection at cookline and food prep receptacles in the	ME+E	Electrical - Distribution Syst	4	4	4	4		\$ 2,872	\$ 3,446	\$ 4,136	\$ 4,652.64
	m		kitchen	IVILTE	Electrical - Distribution Syst	'	'	'	'		Φ 2,012	J 3,440		
	Gymnasiu		Add grounding conductors to all circuits	ME+E	Electrical - Distribution Syst	-1	1	1	-1		\$ 82,992	\$ 99,590	\$ 119,508	\$ 134,447.04
	m			IVILTL	Liectrical - Distribution Syst	'	'	'	'			φ 55,550		
	Gymmasiu		Add fire alarm notification devices at woodshop	ME+E	Fire/Life Safety - Fire Alarm	1	1	1	1		\$ 3,480	\$ 4,176	\$ 5,011	\$ 5,637.60
	Gyriffiasiu		Strut column baseplates below floor beams added in 1996 renovation	HCDA	Structure	1	2	1	2	0	\$ 4,000	\$ 4,800	\$ 5,760	\$ 6,480.00
	Gymnasiu		Replace 1996 gas piping	ME+E	Dhumbing	2	4	2	4	_	c 40.442	\$ 12,532	\$ 15,038	\$ 16,917.66
	m			IVIC+C	Plumbing	2	'	2	4	U	\$ 10,443	ψ 12,532		
	Gymnasiu		Repair existing metal siding where damaged on North and East side	RTA	Exterior - Wall	1	2	3	6		\$ 24,000	\$ 28,800	\$ 34,560	\$ 38,880.00
	Gymnasiu		Repaint the exterior of the building and exposed foundation wall	RTA	Exterior - Wall	1	2	3	6		\$ 10,000	\$ 12,000	\$ 14,400	\$ 16,200.00
	Gymnasiu		Replace all Exterior HM doors, frames and hardware	RTA	Exterior - Door	1	6	1	6		\$ 48,300	\$ 57,960	\$ 69,552	\$ 78,246.00
	Gymnasiu		Install soffit material at the building entry to protect structure	RTA	Exterior - Other	2	2	3	12		\$ 2,000	\$ 2,400	\$ 2,880	\$ 3,240.00
	Gymnasiu		Add emergency power off means at the woodshop and kiln spaces	ME+E	Electrical - Distribution Syst	1	3	4	12		\$ 23,050	\$ 27,660	\$ 33,192	\$ 37,341.00
	Gymnasiu		Provide egress lighting at south gym and art room south exit doors	ME+E	Electrical - Lighting System	4	3	1	12		\$ 1,039	\$ 1,247	\$ 1,496	\$ 1,683.18
	Gymnasiu		Tuck poiunt and repair damaged masonry on the south face of the	HCDA	Structure	2	2	3	12	0	\$ 9,000	\$ 10,800	\$ 12,960	\$ 14,580.00
	Gymnasiu		Add redundant boiler	ME+E	HVAC System	4	2	2	16	0	\$ 41,374	\$ 49,649	\$ 59,579	\$ 67,025.88
	Gymnasiu		Replace existing poured epoxy flooring in the showers	RTA	Interior - Flooring	1	6	3	18		\$ 2,640	\$ 3,168	\$ 3,802	\$ 4,276.80
	Gymnasiu		Cracks in exposed exterior face of concrete foundation walls - cracks	HCDA	Structure	3	2	3	18	4	\$ 18,000	\$ 21,600	\$ 25,920	\$ 29,160.00
	Gymnasiu		Install new Elevator in existing shaft to provide accessible connection	RTA	ADA	1	5	4	20		\$ 90,000	\$ 108,000	\$ 129,600	\$ 145,800.00
	Gymnasiu		Provide a wall partition and serving line between the Kitchen and the	RTA	Interior - Other	1	4	5	20		\$ 40,860	\$ 49,032	\$ 58,838	\$ 66,193.20
	Gymnasiu		Replace 1996 fan coils	ME+E	HVAC System	2	6	2	24	0	\$ 139,728		\$ 201,208	\$ 226,359.36
	Gymnasiu		Renlace Gvm gas fired units	ME+E	HVAC System	2	6	2	24	0	\$ 150,000	\$ 180.000	\$ 216,000	\$ 243.000.00

Condition Matrix

Conditions Analysis Matrix

					С	ontengency Amount		15.00%
						Soft Cost:		20.00%
REMAINING	cos	T (Direct Cost)	cos	ST (w/ Fees & GC	тот	AL COST	тот	TAL COST
LIFE (YEA ▼	(no s	oft costs)	(no	soft costs)	(97:	soft costs)	(w/	contengenc ▼
						-		
Condition		Totals		Totals		Totals	(Grand Totals
0-25	\$	721,420	\$	865,704	\$	1,038,845	\$	1,168,700
26-50	\$	683,102	\$	819,722	\$	983,667	\$	1,106,625
51-100	\$	264,232	\$	317,078	\$	380,494	\$	428,056
> 100	\$	218,713	\$	262,456	\$	314,947	\$	354,315
Totals ->	\$	1,887,467	\$	2,264,960	\$	2,717,952	\$	3,057,697




Ouray School District

Deferred Maintenance Ranking


(inc. soft cost factor and contengency)

Total w/o Escalation: \$3,057,697



Step Two:

Assessing Educational Adequacy Safety & Security



1	Property Boundary & Traffic Flow					
		Total Score	66	out of	92	72%
2	Outdoor Spaces & Amenities					
	Outdoor Spaces & Americaes	Total Score	42	out of	60	70%
		Total Score		- Car cy		1
3	Admin & Staff Spaces					
		Total Score	63	out of	96	66%
4	Restrooms					
		Total Score	8	out of	16	50%
_						
5	Kitchen / Cafeteria	7.10				5004
		Total Score	14	out of	24	58%
6	Main Gymnasium					
		Total Score	16	out of	36	44%
7	Laskan Baama					
	Locker Rooms	Total Score	17	out of	20	61%
		Total Score	17	out of	28	01/0
8	Shop/CTE Lab					
		Total Score	16	out of	32	50%
9	Art Classroom					
<u> </u>	Art classicom	Total Score	19	out of	24	79%
		Total score		- Cut of		1
10	Music Program					
		Total Score	29	out of	36	81%
11	Core Building Spaces Overall					
	core zamamig eparete e teram	Total Score	32	out of	48	67%
				 		
12	Safety & Security					
		Total Score	170	out of	244	70%


Restrooms

- No all Gender restrooms provided
- No direct access for Art/Shop students without going outside and having to re-enter the building
- Limited ability for staff to supervise this area

Kitchen/Cafeteria

- Separate building is not ideal with students crossing the street to access
- Playground is across the street from Cafeteria not ideal for supervision and function
- Cafeteria not separated from Kitchen limiting space use for other functions
- Lacks adequate freezer/cooler space








Main Gymnasium

- No full size practice cross-courts
- Lack space for cheer and other athletic practices
- No Auxiliary Gym to facilitate multiple practices
- Fitness room is small and located on second level where structurally not ideal
- Lack of storage space
- Lack of Elevator (access works, but not ideal)
- No concessions Area
- No appropriate room for officials


Locker Rooms

- Locker Rooms not easily monitored
- Group showers are provided vs. individual stalls
- No direct access to restrooms by visiting teams



Shop/CTE (wood working program)

- Lack of dedicated room (shared with Art)
- Space is too small for tools and workspace needed
- Mobile dust collection is not ideal
- Shop space lacks adequate project storage
- Feedback is that this space does work for the school and scheduling has been OK



Step Three:

Develop a Space Program




Outdoor Spaces

Cafeteria/Kitchen



What spaces should be included?



Gym


Locker Rooms





Weights/Fitness

Sports Turf






Art Room

Music





Flexible Learning Spaces at Ridgway Elementary





Shop/CTE


Others:


- 1. Wood Shop
- 2. Trades
- 3. ???

Popular CTE Programs in Colorado High Schools

- 1. Outdoor Recreation & Natural Resources
- 2. Hospitality & Tourism
- 3. Construction Trades
- 4. Health Sciences
- 5. Agriculture & Environmental Science
- 6. Manufacturing (Woods & Metals)

Flexible spaces to support multiple programs







SITE INFORMATION

ADDRESS: 400 7TH AVE

OURAY, CO 81427

MAIN BUILDING AREA: 42,340 SF GYM & CAFETERIA: 17,800 SF PLAYGROUND: 12,533 SF PARKING LOTS: 8,773 SF

TOTAL SITE AREA: 1.24 ACRES

KEY PLAN LEGEND

- MAIN BUILDING
- 2. GYM AND CAFETERIA
- 3. PLAYGROUND
- 4. SCHOOL PROPERTY
- STREET PARKING
- 6. RESERVED FOR SCHOOL BUSES

SITE PLAN LEGEND

- - - SITE BOUNDARY



PERMANENT BUILDING



BUS PICK-UP & DROP-OFF




PARENT PICK UP & DROP-OFF




PEDESTRIAN CIRCULATION ON CROSSWALKS




MAIN ENTRY





Second Floor





Step Four:


Conceptual Design Options



ADDRESS CRITICAL MAINTENANCE


\$3M

\$



Second Floor

- MAINTENANCE
- FIRE ALARM & SPRINKLER
- HVAC SYSTEMS REPLACEMENT
- ELECT / PLUMBING UPGRADES
- ELEVATOR
- MINOR INTERIOR RENOVATIONS



First Floor

Pros

Lowest Initial Cost Minimal Disruption

Cons

Does not Address Functional Issues

Does not Address Snow/Ice


Defers Major Investment



ADDRESS CRITICAL
MAINTENANCE &
RENOVATIONS


\$4-7M

\$\$



Second Floor

- MAINTENANCE
- FIRE ALARM / SPRINKLER
- MEP SYSTEMS REPLACEMENT
- ELEVATOR
- INTERIOR RENOVATIONS
- ENVELOPE REPLACEMENT



First Floor

Pros

Low Initial Cost

Cons

Does not Address Functional Issues

Does not Address Snow/Ice

Invests in Old Structure

Risks with Old Building


PEMB is Challenging



REPLACE THE EXISTING BUILDING (29k sf)

\$25-30M

\$\$\$\$



Pros

Addresses Function Needs
Create Cohesive Architecture
Modernize Facilities
Improve Energy Perf.


Cons

High Initial Cost

Requires Grant Funding

Displace Gym/Cafe etc. for


over 1 Year



REPLACE GYM BUILDING
ON PLAYGROUND SITE
AND BUILD NEW
PLAYGROUND ON SOUTH
PROPERTY

\$25-33M

\$\$\$\$




Pros

Addresses Function Needs
Create Cohesive Architecture
Modernize Facilities
Improve Energy Perf.
Gym/Cafe. Phasing

Cons

High Initial Cost
Requires Grant Funding
Displace Playground for over 1
Year

What Else?





If I had to pick today, my preferred option is?

(A) Option 1: Address Maintenance Items Only	
	0%
(B) Option 2: Renovate the Gym Building	
	0%
(C) Option 3: Replace the Existing Building on Existing Site	
	33%
(D) Option 4: Replace Gym on Playground	
	56%
(E) Option 5: New Gym on SW Property + Renovation	
	0%
(F) Option 6: New Gym on SW Property + New Cafe/Kit/CR Bldg	
	0%
(G) Option 7: Renovate Gym + New Academic Building	
	0%
(H) Other:	
	11%

Step Five:

Funding Options

Bonding Capacity: \$19M Maximum

\$19M (15 mills in 2026)

Residential: \$100/yr/100k

Commercial: \$405/yr/100k

\$10M (8 mills in 2026)

Residential: \$54/yr/100k

Commercial: \$216/yr/100k

B.E.S.T. Building Excellent Schools Today

What is BEST?

Collaboration by CO legislative leardership, Gov. Bill Ritter, former State Treasurer Cary Kennedy, and a large coalition worked together on this for their ambitious and landmark legislation

The BEST legislation addresses health and safety issues by providing funds to rebuild, repair or replace the most needy K-12 facilities. The BEST plan calls for assessment, an expert-guided process for the selection of funding projects, and the spending of up to \$1 billion in funds without raising taxes;

Hazards and issues being addressed included: failing roofs, structural problems, inadequate fire safety, faulty and dagerous boilers, asbestos, code issues, inadequate educational suitability, overcrowding, faulty and dangerous electrical service, poor indoor air quality, lack of ADA accessibility, and carbon monoxide contamination.

Priority 1

This application addresses safety hazards or health concerns at existing public school facilities, including concerns relating to public school facility security, and projects that are designed to incorporate technology into the educational environment. See glossary for definition of "technology".

Priority 2

This application will relieve current overcrowding in public school facilities, including but not limited to allowing students to move from temporary instructional facilities into permanent facilities.

Priority 3

This application will provide career and technical education capital construction in public school facilities.

Priority 4

This application will assist in the replacement of prohibited American Indian Mascots

Priority 5

This application is for other types of capital improvements not addressed in priorities 1-4.

3 types of BEST grants:

BEST Cash Grants [Fund smaller projects]

2 BEST Lease Purchase Grants [Fund larger projects]

Ouray Qualified match:

Bonding Capacity:

55% \$19N

BEST Emergency Grants
[Unanticipated events]



Ouray ES/MS/HS Gym & Cafeteria

Address: 400 7th Avenue

Ouray, CO 81427

Size: 17,800

Stories: 2

Asset Type: Building

Functional Description: Combined School


Year Constructed: 1965

Assessment Date: Sep 3, 2020

FCI: 0.52

Replacement Value: \$6,421,139





Note: Hover over chart elements to see detailed information Click legend elements to hide/show data





^{*} This asset has been assessed.

BEST GRANT OVERVIEW

Preparation

July - December 2023

- Awarded FY23-24 projects begin work.
- Potential applicants work with consultants and BEST staff to define project scope and develop budget.
- Notifications for upcoming grant cycle published.
- No later than November 30: All
 Districts and Charter Schools must
 notify BEST of intent to apply.
- Final FY23-24 project list is established based upon November election results.
- December 30, 2023: FY23-24 Grant
 Agreements not fully executed may be rescinded in order to fund backup projects.

Application

January 2024

- · Match percentages available.
- Online training available.
- Applicants assigned Grant Manager accounts to submit applications.
- January 8 February 5: Application open, submissions due at 4 pm on February 5th.

Approvals

February - June 2024

- February 6 April 18: Staff review of FY24-25 applications. Summary Book published. Conditional Commitment Vouchers delivered.
- April 18 May 13: Capital Construction Assistance Board (CCAB) review period.
- May 13 May 15: CCAB meets to prioritize recommended projects for FY24-25.
- No later than June 20: State Board of Education (SBE) meets to approve prioritized list.
- No later than July 15: Capital
 Development Committee meets to approve SBE Lease Purchase project recommendations.

Planning Advisory Team Meeting Outline

Meeting #	Date	Agenda
1	6.20.2024	PAT Kick-off / Assessment Field Work
2	9.18.2024	Data Review / Program Ideas / Discuss Options
3	10.1.2024	Review Master Plan Options / Draft Program
4	11.5.2024	Present Master Plan Recommendations to BOE

Ouray School District:

Initial Goals for Master Plan

- Stakeholder input is important
- Thoughts around CTE programs (maybe survey)
- Band room: Look at safety around acoustics and room design
- Separate wood shop and art
- Weight Room is not appropriate
- Interested in stakeholder input into what new programs could be included

