Maintenance Warehouse



930 Colorado Ave, Montrose, CO 81401

Year Built: 2007

Site Area: 588,300 sf / 6.6 acres (Including ECC Main Campus)

Number of Permanent Buildings: 1

Total Building Area: 9,960 sf

Current Staffing: 17

Description of Facility: Facilities, Custodial, Food Service Offices, Maintenance Shops, and District warehouse





1" = 160'-0"

MAINTENANCE WAREHOUSE

scale: 1" = 160'-0"

KEY PLAN LEGEND


- 1. MAINTENANCE WAREHOUSE BUILDING
- 2. STAFF PARKING
- 3. DISCTRICT OFFICE BUILDING
- 4. OUTER RANGE PROGRAM
- 5. EARLY CHILDHOOD CARE MAIN CAMPUS

SITE PLAN LEGEND

_____ SITE BOUNDARY

PERMANENT BUILDING FOOTPRINT

MODULAR BUILDING FOOTPRINT




MAINTENANCE WAREHOUSE EXISTING SITE PLAN











FLOOR PLAN - CAPACITY	
1" = 20'-0"	





MAINTENANCE WAREHOUSE EXISTING FLOOR PLAN



20'

3.2 Condition Analysis Matrix

		Indiysis wid										
Project:		County School Dis										
Facility:		ce/Warehouse (MW)									
Date:	2/7/2022											
Failure Timing	-		2									
1	The item will fail or has already failed (Red) Replace within 5 Years (Orange)											
2 3	•	tin 5 Years (Orange tin 6-10 Years (Yell					(see scorin	g tab for detail	e)			
4			o indicate remaing years of system life				(300 300111		3)			
	-											
Condition Matrix												
ITEM #	FACILITY	LOCATION	ITEM DESCRIPTION	CONSULTANT	ITEM CATEGORY	FAIL TIMING	САТ	CONSQ	FINAL RANK	REMAINING LIFE (YEARS)	COST (Direct	
1	MW	INT	Replace carpet in Rms, 10, corridor, conference room	RTA	Flooring System	2	6	6	72	· · · ·	\$	10
2	MW	INT	Provide lighting controls	RTA	Lighting System	2	6	6	72		\$	31
3	MW	INT	Provide urinal screen in men's restroom	RTA	Code/ADA	1	3	4	12		\$	1
4	MW	INT	Provide ADA compliant signage-not grade II braille	RTA	Code/ADA	1	5	4	20		\$	2,
5	MW	INT	Provide ADA compliant stall in Women's restroom	RTA	Code/ADA	1	5	4	20		\$	1,
6	MW	INT	Lower all toilet paper dispenser below grab bar in ADA stalls	RTA	Code/ADA	1	5	4	20		\$	
7	MW		Provide compliant sink, faucet, and counter height in Break room	RTA	Code/ADA	1	5	4	20		\$	5,
8	MW		Provide panic bar at north exit door next to overhead doors.	RTA	Code/ADA	1	3	4	12		\$	
9	MW		Provide closure at back of risers for stairs in carpenter shop	RTA	Code/ADA	1	3	4	12		\$	2,
10	MW		Provide guardrail at mezzanine stairs in carpenter shop	RTA	Code/ADA	1	3	4	12	_	\$	3,
11	MW		Provide access ladder to mezzanine in ground shop	RTA	Other	3	6	6	108		\$	1,
12	MW	wide	Fire sprinkler riser located in south end of building. Building has a wet fire sprinkler throughout. No upgrades anticipated.	Bighorn	Other	4	11	8	352			
13	MW	Admin Area	There is a ground mounted, packaged heating and cooling unit (5-ton) on the SW corner of the building that serves the office/admin area of the building. Unit appears to date to 2006. Unit is near end of life and should be replaced.	Bighorn	HVAC System	2	11	3	66		\$	32,
14	MW		Building is served by gas-fired unit heaters and exhaust fans that date to 2006. Unit heaters are nearing end of life.	Bighorn	HVAC System	3	11	7	231		\$	67,
15	MW	Building wide	Electric water heater in janitor closet. 40 gallon Rheem unit. Appears to date to 2006.	Bighorn	Potable Water System	3	11	7	231		\$	1,
16	MW		Gas piping is routed to each building from a campus wide gas meter. Piping is underground, rises at exterior with gas regulator.	Bighorn	Other	4	11	8	352		\$	18,
17	MW	Building wide	The electrical service is adequate for this type of occupancy	Bighorn	Electrical Power System	4	11	8	352		\$	51,
18	MW		The lighting is adequate for this type of occupancy and has been improved with replacement LEDs	Bighorn	Lighting System	4	11	8	352		\$	57,
19	MW		Asphalt Parking (17,000 sqft)	Delmont	Pavement System	4	11	7	308		\$	14,
20	MW	South	Concrete Loading dock (6,500 sqft)	Delmont	Concrete System	4	11	7	308			
21	MW	North	Gravel Lot (29,000 sqft)	Delmont	Other	2	7	6	84		\$	40,
											<u> </u>	
										ļ		L

		•	
Condition	Totals		
0-25	\$	16	
26-50	\$		
51-100	\$	114	
> 100	\$	213	
Totals ->	\$	344	

Date of last addition: NA

Year round start date:___

		Co	intengency Amount		15.00%
			Soft Cost:		20.00%
	COST (w/ Fees & GC's)	TOTAL COST			AL COST
	(no soft costs)	(w/ soft			contengency)
10,444	\$ 12,011	\$	14,413	\$	16,215.00
31,158	\$ 35,832	\$	42,998	\$	48,372.80
1,350	\$ 1,553	\$	1,863	\$	2,095.88
2,000	\$ 2,300	\$	2,760	\$	3,105.00
1,200	\$ 1,380 * 1,025	\$	1,656	\$	1,863.00
900	\$ 1,035 \$ 6,325	\$ \$	1,242	\$ \$	1,397.25
5,500		э \$	7,590 690	э \$	8,538.75 776.25
500 2,000	\$ 575 \$ 2,300	ъ \$	2,760	э \$	3,105.00
3,000	\$ 3,450	\$	4,140	\$	4,657.50
1,500	\$ 3,430 \$ 1,725	\$	2,070	\$	2,328.75
1,000	· · · · · · · · · · · · · · · · · · ·	φ \$	2,070	φ \$	2,020.75
	\$-	Ψ	_	Ψ	
		\$	44,850	\$	50,456.25
32,500	\$ 37,375	·	,	, ,	
67,736	\$ 77,897	\$	93,476	\$	105,160.53
57,750	ψ 11,031				
1,800	\$ 2,070	\$	2,484	\$	2,794.50
18,750	\$ 21,563	\$	25,875	\$	29,109.38
51,930	\$ 59,720	\$	71,663	\$	80,621.33
57,123	\$ 65,691	\$	78,830	\$	88,683.46
14,450	\$ 16,618	\$	19,941	\$	22,433.63
,	\$ -	\$	-	\$	-
40,600	\$ 46,690	\$	56,028	\$	63,031.50
	Tatala		Tatala		
6 450	Totals	Totals			Grand Totals
6,450	\$ 18,918	\$	22,701	\$	25,539
-	\$- \$131.008	\$ ¢	-	\$ ¢	-
4,702	\$ 131,908 \$ 245,283	\$ ¢	158,289	\$ \$	178,076
3,289	\$ 245,283 \$ 396,108	\$ \$	294,339	ъ \$	331,132 534,746
4,442	φ 390,108	φ	475,330	φ	554,740